




Forward Proton Detector



Carley Martins
Dzero/FPD
On site activities





Forward Proton Detector



Dzero and FPD operation

- Shifts (FPD & Calorimeter)
- Plastic frame construction
- High helium levels on PMT
- Electronic setting on SMR

FPD Hardware


- Detector configuration
- FPD integration
 - => trigger & readout



Forward Proton Detector



FPD Trigger and Readout




Forward Proton Detector

FPD Integration


Trigger manager
cable & boards:
(Collision Hall to Movable
Counting House).

- MRC



Transition Patch Panel (TPP) boards and AFE
(Rack PW08 on Collision Hall)

Very small space to accommodate cables and boards inside rack !!





Forward Proton Detector





TPP: Noise Problem

Timing for FPD => Pedestal runs and calibration


Dipole

A1 Up



Noise Problem


- Amplifier shape
- Ribbon cables
- transformers
- TPP
- Flex cable
- AFE







Ribbon cables status

Ribbon cables tests
For A1_up:
return lines for all
channel was
checked

**~ 10% of the total
channel was dead**



Forward Proton Detector





Forward Proton Detector



Detectors cable configurations

Ribbon cables

- for dipoles => two segments
no (significant) noise
- for others detectors => one segment
significant noise

**Grande
mistério
!?!?!?!?**

**In the access to Collision Hall we noticed a
connection between both ground planes of dipole board
(electronic and tunnel ground)**



Forward Proton Detector



TPP dipole with electronic and tunnel ground disconnected, shown the same noise pattern!

Final conclusion

TPP needs to be redesigned to take in account the electric characteristics of of AFE boards

Noise report @

http://d0server1.fnal.gov/projects/FPD/Hardware/Trigger/AFE/NoiseProblems/Report1_2003Jun11_a.doc